

An aerial photograph of the Buncefield oil depot disaster. A massive, dark, billowing plume of smoke and ash rises from a central point of fire. Below the smoke, several large white and green storage tanks are visible, some of which appear to be damaged or on fire. The surrounding area includes roads and other industrial structures.

# **Buncefield Incident – Some Lessons Learnt**



# Motivation

- The Buncefield Incident in 2005 was the most severe explosion and fire in Europe after World War II
- The operators of the oil storage terminal were prosecuted and fined for their roles
- What are some of the lessons that can be learnt from that incident?



# Dr Fathi Tarada


- Expert witness in criminal trial against Hertfordshire Oil Storage Ltd (HOSL) and British Pipeline Agency Limited (BPA)
- Appointed by the Competent Authority (Health & Safety Executive and Environment Agency)
- First public presentation of my findings



# Contents

- Background to the incident
- Scope of expert witness role
- Secondary containment
- Tertiary containment
- Recommendations

# Background to the Incident





# Cause of Incident

- Overflow of Tank 912 due to faulty gauge
- High-level switch also failed
- 300 tonnes of petrol spilled through tank's roof vents
- Vapour quickly flowed out of bunds and off the site, at 2m depth
- Unconfined vapour cloud explosion of unusually high strength



# Incident Progression

- Large initial explosion from HOSL's tank T912, and consequent fire
- Fire spread over 22 fuel storage tanks and 7 bunds
- Six tanks on adjoining British Pipeline Agency Limited (BPA) site also involved in fire



# Casualties

- Fire burned for 3 days
- 43 people injured (two hospitalised)
- Extensive property damage




# Initial Fireball



# Seismic Activity (Richter Scale 2.4)

Start: 12/11/05 6:00:52 UTC Station: HHUK 51.778N 0.0150000W Samples: 3161 SPS: 20  
Comment: 26km from HHUK. Max/Min: 787.4/-743.9 X: 2.37.0 Y: 800c  
Event Time: 12/11 06:01:31.0 Lat/Long: 51.772N 0.395W Depth: 0km 0.0mi Mag: Ms321.76 Mb0.59 Mw5.12 Md-27.28



# Police Helicopter View





# Temperature Inversion



# Fuji Building





# Scope of Expert Witness Reports

For HOSL and BPA sites, review of:

- Secondary containment (bund integrity)
- Tertiary containment (site profiling and drainage)



# Bund Joints



# No Reinforcement Steel through Joints





# Failed Rubber Gasket



# Obtuse Bund Angles





# Spalled Bund Joint



# Shielding Effect of Steel Plate






# Tie Bar Holes



# Escape of Product & Firewater





# Bund Joints – Key Issues

- Standards not adhered to
- Waterstops missing
- No reinforcement steel through joints
- Obtuse angles between bund sides
- Shielding of joints would have assisted in protecting them



# Bund Penetrations





# Destroyed Pipework



# Fire-Fighting





# Tank Collapse



# Foam Application







# Escape of Fire-Fighting Water & Foam



# Aerial View





# Escape of Product and Firewater





# Cherry Trees Lane



# Roundabout at Cherry Tree Lane





# Contamination of Drainage System



# Soakaway





# Contamination





# Tertiary Containment

- Drainage system had limited capacity, and led to soakaways.
- The fire water lagoon had an intrinsic flaw in that it flooded the fire pump house when it was full.
- The site topography was not suitable for retention of petroleum products on site, since any flow would naturally go down Cherry Tree Lane.



# Specific Recommendations

- Loss of secondary containment:
  - Bund joints
  - Tie bar holes
  - Pipe penetrations
- Tertiary containment



# Other Recommendations

- Loss of containment (indication switches)
- Emergency arrangements
- Safety management systems, managerial oversight and leadership





# Thank You

Dr Fathi Tarada  
Mosen Ltd