

Buncefield: Why did it happen?

The underlying causes of the explosion and fire at the Buncefield oil storage depot, Hemel Hempstead, Hertfordshire on 11 December 2005

Contents

Foreword	3
Executive summary	4
Introduction	6
The Buncefield oil storage depot	7
The incident and its aftermath	10
Root causes of the loss of containment	13
The independent high-level switch	13
The automatic tank gauging system	14
Other shortcomings	14
Wider underlying causes	16
Control of incoming fuel	16
Increase in throughput	16
Tank filling procedures	17
Pressure of work	18
Inadequate fault logging	19
Motherwell Control Systems	19
Loss of secondary containment	21
Bund joints	21
Tie bar holes	22
Pipe penetrations	22
Tertiary containment	24
Emergency arrangements	26
Safety management systems, managerial oversight and leadership	27
Management of the HOSL site	28
Conclusions	30
Appendix 1 How the independent high-level switch (IHLS) worked	32
Appendix 2 Outcome of criminal proceedings	34
Glossary	35
References	36

Foreword

The Major Incident Investigation Board (MIIB) set up to investigate the Buncefield explosion and fire completed its work in 2008 and published its final report.¹ At that time it was not possible to disclose all the information about the underlying causation upon which many of its recommendations were based as criminal legal proceedings were still in progress. However, now that these proceedings have concluded, this information can be brought together so that everyone in major hazard industries – not just those involved in fuel storage – can learn from this incident, understand what went wrong, and take away lessons that are relevant to them. Although five years have passed since the incident, the information and advice in this report is still highly relevant today.

The explosion and fire at the Buncefield oil storage depot in 2005 was a significant event. As part of the work of the MIIB, the Health and Safety Executive and the Environment Agency, as the Competent Authority in England and Wales for the regulation of major accident hazards, carried out a joint investigation into the cause of the incident.


The Competent Authority took action to ensure that those responsible for the incident were held to account in the criminal courts, and I emphasise our determination that, where we think it appropriate, the Competent Authority will continue to take the necessary action to ensure operators of major hazard sites manage them properly. When passing sentence on the defendants at St Albans Crown Court on 16 July 2010, the Judge, the Hon Mr Justice Calvert-Smith, commented that cost cutting *per se* was not put forward as a major feature of the prosecution case, but the failings had more to do with slackness, inefficiency and a more-or-less complacent approach to matters of safety.

I therefore ask all in the major hazard industries to look carefully at your own operations in the light of the management and technical failings that lay behind this incident, and the important developments in the meantime.

Since the incident, the Competent Authority, industry and trade unions have worked together to drive forward high standards at fuel storage sites. This has resulted in agreement on improved standards of safety and environmental protection for all UK sites storing large volumes of gasoline and to systematically upgrade sites to meet these standards, with progress monitored by the Competent Authority as part of its regulatory programmes. This work has also established a set of process safety leadership principles for top-level engagement in all businesses involved with significant risks to people and the environment – see www.hse.gov.uk/comah/buncefield/response.htm.

The Competent Authority has also improved its approach to regulating onshore major hazards in the light of ten years of operating the COMAH regime including incidents such as Buncefield. More information on the Competent Authority's remodelling programme is at www.hse.gov.uk/comah/remodelling/index.htm.

Major industrial incidents are thankfully rare and I trust this report will contribute to making them even rarer.



Gordon MacDonald
Chairman
Competent Authority Strategic Management Group

Executive summary

On the night of Saturday 10 December 2005, Tank 912 at the Hertfordshire Oil Storage Limited (HOSL) part of the Buncefield oil storage depot was filling with petrol. The tank had two forms of level control: a gauge that enabled the employees to monitor the filling operation; and an independent high-level switch (IHLS) which was meant to close down operations automatically if the tank was overfilled. The first gauge stuck and the IHLS was inoperable – there was therefore no means to alert the control room staff that the tank was filling to dangerous levels. Eventually large quantities of petrol overflowed from the top of the tank. A vapour cloud formed which ignited causing a massive explosion and a fire that lasted five days.

The gauge had stuck intermittently after the tank had been serviced in August 2005. However, neither site management nor the contractors who maintained the systems responded effectively to its obvious unreliability. The IHLS needed a padlock to retain its check lever in a working position. However, the switch supplier did not communicate this critical point to the installer and maintenance contractor or the site operator. Because of this lack of understanding, the padlock was not fitted.

Having failed to contain the petrol, there was reliance on a bund retaining wall around the tank (secondary containment) and a system of drains and catchment areas (tertiary containment) to ensure that liquids could not be released to the environment. Both forms of containment failed. Pollutants from fuel and firefighting liquids leaked from the bund, flowed off site and entered the groundwater. These containment systems were inadequately designed and maintained.

Failures of design and maintenance in both overfill protection systems and liquid containment systems were the technical causes of the initial explosion and the seepage of pollutants to the environment in its aftermath. However, underlying these immediate failings lay root causes based in broader management failings:

- Management systems in place at HOSL relating to tank filling were both deficient and not properly followed, despite the fact that the systems were independently audited.
- Pressures on staff had been increasing before the incident. The site was fed by three pipelines, two of which control room staff had little control over in terms of flow rates and timing of receipt. This meant that staff did not have sufficient information easily available to them to manage precisely the storage of incoming fuel.
- Throughput had increased at the site. This put more pressure on site management and staff and further degraded their ability to monitor the receipt and storage of fuel. The pressure on staff was made worse by a lack of engineering support from Head Office.

Cumulatively, these pressures created a culture where keeping the process operating was the primary focus and process safety did not get the attention, resources or priority that it required.

This report does not identify any new learning about major accident prevention. Rather it serves to reinforce some important process safety management principles that have been known for some time:

There should be a clear understanding of major accident risks and the safety critical equipment and systems designed to control them.

This understanding should exist within organisations from the senior management down to the shop floor, and it needs to exist between all organisations involved in supplying, installing, maintaining and operating these controls.

There should be systems and a culture in place to detect signals of failure in safety critical equipment and to respond to them quickly and effectively.

In this case, there were clear signs that the equipment was not fit for purpose but no one questioned why, or what should be done about it other than ensure a series of temporary fixes.

Time and resources for process safety should be made available.

The pressures on staff and managers should be understood and managed so that they have the capacity to apply procedures and systems essential for safe operation.

Once all the above are in place:

There should be effective auditing systems in place which test the quality of management systems and ensure that these systems are actually being used on the ground and are effective.

At the core of managing a major hazard business should be clear and positive process safety leadership with board-level involvement and competence to ensure that major hazard risks are being properly managed.